



Paisley Farms - learn how a silicone coating system (not paint) was the best option for exterior walls.

PROJECT INFORMATION

Project Year: 2024

Project Size: 16,465 sq ft.

Project Location: Willoughby, OH

Days to Complete: 24

Project Overview: Silicone Coating over existing exterior walls.

Manufacturer Used (Coating):

Progressive Materials

Paisley Farms is a three-building, high-quality vegetable processing company located in Willoughby, Ohio since 1945.

During an inspection of the current spray polyurethane foam roof system on each of the buildings, a major concern of deep degradation, wall cracking, and scaling paint on the concrete block walls was discovered.

The owner, originally thinking paint would fix the issues, was presented with a solution to install a silicone wall coating system.

Utilizing fibered sealants and high-solids silicone coating, the system would eliminate any further deterioration and seal the walls entirely.

Though a more expensive route to take, the long-standing facility would be restored with the strength to continue for years to come.



